

	REGOMS TREATING IRONS		
NO	DESCRIPTION	LENGTH	QUANTITY
1	2" FIG 1502 STRAIGHT JOINT WxT	9FT	3
2	2" FIG 1502 STRAIGHT JOINT WxT	6FT	1
3	2" FIG 1502 STRAIGHT JOINT WxT	5FT	2
4	2" FIG 1502 STRAIGHT JOINT WxT	2FT	3
5	2" FIG 1502 HARD 90 WxT		11
6	2" FIG 1502 2WAY STYLE NO.50 WxT		10
7	2" FIG 1502 2WAY STYLE NO.10 WxT		1
8	3" FIG 1502 2WAY STYLE NO.50 WxT		3
9	3" FIG 1502 TEE WxTxT		3
10	2" FIG 1502 TEE WxTxT	2FT	3
11	3" CHOKE		1
12	2" FIG 1502 2x1 PLUG VALVE WxT		1
13	2" FIG 1502 2x2 PLUG VALVE WxT		1
14	4" FIG 1502 ELBOW WxT		2
15	4" FIG 1502 FLANGE x W		1
16	4" FIG 1502 FLANGE x THREAD		1
17	6" FIG 1502 FLANGE x WING		1
18	HAMMER UNION 6" FIG SARA-SAE THREADED		11
19	HAMMER UNION 4" FIG SARA-SAE THREADED		17
20	2" FIG 1502 STRAIGHT JOINT WxT	10FT	6
21	2" FIG 1502 STRAIGHT JOINT WxT	4FT	1
22	2" FIG 1502 PUP JOINT WxT	2FT	2
23	2" FIG 1502 HARD 90 WxT		3
24	2" FIG 1502 TEE WxTxT		1
25	2" FIG 1502 Y JOINT WxTxT		1
26	2" FIG 1502 2x1 PLUG VALVE WxT		1
27	2" FIG 1502 2WAY SWIVEL JOINT WxT		1
28	2" FIG 1502 STRAIGHT JOINT WxT	8FT	2
29	2" FIG 1502 STRAIGHT JOINT WxT	5FT	2
30	2" FIG 1502 TEE TxWxT		1
31	2" FIG 1502 TEE TxTxW		1
32	2" FIG 1502 2WAY SWIVEL JOINT WxT		1